




AF27.19-P-6101C	Transmission fails to shift to 4th gear	1.9.92
-----------------	-----------------------------------------	--------

TRANSMISSION 722.5 in MODEL 124, 129, 140, 210

Modification notes

26.8.98	Validity updated		
---------	------------------	--	--

Damage code	Cause	Remedy:	
27 216 73	Solenoid coil in control valve makes poor contact. Fault code readout  9 Control valve (Y3/1y2)	1 Read out transmission DTC memory.	dh0202pf00012x
		2 Erase fault memory.	AD00.00-P-2003A
		3 Test drive vehicle (check 4th gear shift).	
		 If 4th gear is not shifted: ↓	
		4.1 Check control valve (Y3/1y2). Model 124/129 Model 140  If 4th gear shifted: ↓ 4.2 Remove/install/replace control valve (Y3/1y2).	dh0201pf10023x dh0202pf00023x